

Hunters Point Naval Shipyard Radiological Program Update

Derek Robinson

HPNS Environmental Coordinator

HPS CAC Meeting September 11, 2017

Purpose of this Presentation



- Provide general background information on radiological concerns at HPNS
- Provide the current status of the radiological data re-evaluation and answer questions
- 3. Describe future actions to complete the re-evaluation and present results to the public

Hunters Point Naval Shipyard (HPNS) History



Founded as a commercial dry dock

1869

Navy radiological uses

1939 to 1974

Navy ends leasing

1986













1939

Purchased by **US Navy**



Leased to Triple A Machine Shop



Placed on **BRAC list**



HPNS dry docks (1940)



USS Iowa at HPNS (1953)

What Is Radiation?



- Radiation is energy given off from atoms
- Everyone is exposed to radiation every day from natural and man-made sources, including:









Navy Fact Sheet on Radiation exposure available here:

www.bracpmo.navy.mil/hpnsrc

What were the Navy uses of radiation at HPNS?



Historical activities at HPNS

- Ship repair and maintenance
- Testing and decontaminating ships
- Navy Radiological Defense Laboratory (NRDL) testing
- Waste disposal practices

Where are the potentially contaminated areas at HPNS?

- Buildings with historical radiological use
- Sanitary sewer and storm drain lines (removed)
- Former disposal/burial areas
- Piers and ship berths



How does the Navy address radiological contamination at HPNS?









Soil and Sewer Line Removal

- Evaluate by sampling and scanning
- Monitor the environment
 - Air monitoring
 - Perimeter scanning
 - > Equipment and personnel
- Remove sources or construct protective barriers
- Confirm the safety of response
- Report to agencies and the public
- All responses are performed in coordination with
 - > EPA
 - > DTSC
 - ➤ CDPH
 - > SFDPH



Radiological Data Investigation (2012)



Why did the Navy start to question data?

- In 2012, Navy review of radiological sampling data found anomalous results that could not be explained
- The Navy discovered that one of its radiological remediation contractors (Tetra Tech EC), had misrepresented radiological data

What was done after discovery of the misrepresented data?

- Regulatory agencies (NRC, EPA, and CDPH) were notified
- Tetra Tech EC performed an internal investigation, and presented results to the Navy in "Anomalous Soil Sampling Report"

Current Radiological Data Re-Evaluation



Why are radiological sample results being questioned again?

- In 2016, a former Tetra Tech EC employee made new allegations of improper sampling and cleanup activities
- In 2017, six more former Tetra Tech EC employees made further allegations

Current Radiological Data Re-Evaluation




How is the Navy addressing new allegations?

- First priority was to evaluate the allegations and determine whether those who live and work on or near HPNS are being exposed to harmful radiation
 - That evaluation indicated it is safe to live and work here
- The Navy has assembled a team of technical experts to evaluate information and existing data

Size and Scope of Current Evaluation






Data Evaluation Method - Statistics



- Statistical tests are very efficient and can look at a lot of data
- Statistical tests tell us whether the radiological data is genuine or falsified
- •5 types of statistical tests used for soil sampling and building scan data

Example of statistical analysis:

- ✓ The graph shows how often a concentration of Radium 226 was detected in a survey unit.
- ✓ The red line shows the frequency of Radium -226 concentrations for May 31, 2012, and the black line shows the pattern for all other days of sampling the survey unit.
- ✓ This shows that the data collected on May 31, 2012 are not from the same area as all the other samples from the survey unit, and are suspected to be fraudulent.
- This also shows that statistical methods work.




Data Evaluation Method – Logic Tests



- Inconsistencies in data and methods:
 - Samples collected on different day than rest of survey unit
 - Timing on sample collection
 - Samples analyzed before records say they were collected
- Unusual patterns in analytical and scan data

Example of unusual pattern: Ac-228 is a naturally occurring radionuclide, and should be detected within a consistent range within a survey unit. In evaluating data from soil sampling it was determined that Ac-228 concentrations decreased suddenly while sampling for closure of survey unit when compared to previously sampling in the same survey unit.



Key Accomplishments



- Assembled soil database for sewer lines and soil sites
- Evaluated statistical methods and developed a validation protocol with EPA to verify Navy process
 - Completed statistical tests of sewer line and soil sites data
 - Added experts from Oak Ridge Associated Universities to provide support and independent review
 - Developed methods for future sampling

Next Steps



Evaluate

- Continue data evaluation efforts
- Coordinate with agencies
- Consult independent experts

Communicate

- Continue public outreach
- Hold meetings to talk about findings reports
- Regular email newsletters

Sample

- Plans for sampling will be based on findings reports
- Sampling results will be reviewed by Navy and agencies

Report

A Confirmation
 Report that
 discusses
 findings and
 sampling results
 will be
 distributed to the
 public

Is the Community Safe?



- The Navy's first priority is public safety
- The Navy will complete all work to be protective of Human Health and the Environment
- People who live on, work at and visit the HPNS area are safe
- The Navy continues its commitment to ensure that all property at HPNS will be safe before transfer to the City of San Francisco



For more information...



Join the HPNS Mailing List



Send an email to info@sfhpns.com



Leave a message on the HPNS Information Line (415) 295-4742

Navy Resources

City of San Francisco Main Library

100 Larkin Street, 5th Floor Government Information Center San Francisco, CA 94102 (415) 557-4400

BRAC Environmental Coordinator

Derek Robinson 619-524-6026 derek.j.robinson1@navy.mil

Shipyard Site Trailer

(near HPNS security entrance) 690 Hudson Avenue San Francisco, CA 94124

Community Resources

Community Technical Advisor
Dr. Kathyrn Higley
(541) 737-7063 kathryn.higley@oregonstate.edu

Community Liaison
Mr. James Bryant
(415) 970-9051 community@sfhpns.com

Information on the Internet

American Nuclear Society www.ans.org

U.S. Environmental Protection Agency www.epa.gov

U.S. Nuclear Regulatory Commission www.nrc.gov

Hunters Point Navy Website

www.bracpmo.navy.mil/hpns

Radiological Page

www.bracpmo.navy.mil/hpnsrc

World Health Organization www.who.int

Radiation Answers www.radiationanswers.org

American Council on Health and Science www.acsh.org